HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

HAER IND 67-GREC. V, 1-

HAER No. IN-100

Putnam County Bridge #111 (Dills Ford Bridge) On County Road 50 North over Little Walnut Creek Greencastle Vicinity Putnam County Indiana

Photographer: (all views) Camille B. Fife, The Westerly Group, Inc.

- '	February, March 1998
IN-100-01	A LONG VIEW, LOOKING NORTH FROM THE WEST BANK OF LITTLE WALNUT CREEK TOWARD THE SOUTH (DOWNSTREAM) SIDE OF THE BRIDGE.
IN-100-02	A LONG VIEW, LOOKING SOUTH FROM THE LAND BETWEEN LITTLE WALNUT AND LEATHERWOOD CREEKS SHOWING THE WEST HALF OF THE NORTH SIDE OF THE BRIDGE.
IN-100-03	A LONG VIEW, LOOKING SOUTHEAST FROM THE SAME LOCATION AS THE PREVIOUS PHOTO, SHOWING THE EAST HALF OF THE NORTH SIDE OF THE BRIDGE.
IN-100-04	A VIEW LOOKING NORTH FROM THE EAST BANK OF LITTLE WALNUT CREEK. THE NARROW ARCH OF THE SPAN IS CLEARLY SHOWN.
IN-100-05	A MEDIUM CLOSE UP VIEW, LOOKING NORTHWEST, SHOWING THE DOWNSTREAM PIER. THE LABEL CONTAINING THE CONSTRUCTION DATE OF THE BRIDGE IS PART OF THE REMAINS OF THE ORGINAL BALUSTRADE.
IN-100-06	AN IMAGE LOOKING NORTHWEST FROM THE EAST BANK OF THE CREEK, SHOWING THE UNDERSIDE OF THE EASTERN ARCH, THE PIER AND THE STEEL I-SECTIONS USED TO TEMPORARILY REPAIR THE SPANDREL WALLS.
IN-100-07	THIS PHOTO IMAGE LOOKING SOUTHWEST FROM THE LAND BETWEEN THE TWO CREEKS, SHOWS NORTH SIDE OF THE WEST SPAN OF THE BRIDGE, WITH THE TRUNCATED

Putnam County Bridge #111 (Dills Ford Bridge) HAER No. IN-100 (Page 2)

BALUSTRADE AND	STEEL	I-SECTIONS	HOLDING	THE
SPANDREL WALLS	TOGETI	HER.		

	SPANDREL WALLS TOGETHER.
IN-100-08	A MEDIUM RANGE VIEW, LOOKING SOUTHEAST, OF THE UNDER SIDE OF THE EAST SPAN AND THE EAST ABUTMENT.
IN-100-09	A VIEW, LOOKING NORTH/NORTHEAST FROM THE ISLAND SOUTH OF THE BRIDGE TOWARD THE SOUTH SIDE, SHOWING BOTH SPANS.
IN-100-10	THIS PHOTOGRAPH, LOOKING WEST ALONG THE NORTH SIDE OF THE SPAN, SHOWS THE BROKEN EDGE OF THE BALUSTRADE AND A CLEAR PROFILE OF THE UPSTREAM SHEARWATER.
IN-100-11	A VIEW LOOKING EAST ALONG THE SOUTH SIDE OF THE BRIDGE. THE SOLID WALL ON THE ABUTMENT, AND THE REPAIRS TO THE SPANDREL ARE VISIBLE.
IN-100-12	A CLOSE-UP VIEW, UNDERNEATH THE BRIDGE, LOOKING WEST TOWARD THE WEST ABUTMENT AND SHOWING THE DETERIORATED CONCRETE ALONG THE ENTRADOS.
IN-100-13	A CLOSE-UP VIEW FROM THE SAME LOCATION AS THE PREVIOUS PHOTO, LOOKING EAST, OF THE CENTRAL PIER AND THE UNDERSIDE OF THE BRIDGE. BOTH THE NORTH AND THE SOUTH SHEARWATERS ARE VISIBLE, SHOWING THE SLIGHTLY LARGER PROFILE OF THE UPSTREAM PIER.
IN-100-14	A VIEW LOOKING WEST FROM THE EAST ENTRY, ALONG THE ROADBED. THE BRIDGE HAS BEEN CLOSED TO TRAFFIC AT THIS TIME.
IN-100-15	AN IMAGE LOOKING EAST, FROM THE WEST APPROACH TO THE BRIDGE, SHOWING GRAFFITI ON THE WALL ABOVE THE NORTHWEST ABUTMENT.
IN-100-16	A CLOSE-UP VIEW OF THE NORTH SIDE OF THE UPSTREAM SHEARWATER, SHOWING THE WAY IN WHICH THE BRIDGE DESIGNER INTEGRATED THE ROUND BASE WITH THE SHARP-EDGED CUTWATER. ALSO VISIBLE IS THE SIMPLE DECORATIVE BELT COURSE AT THE ROADBED LINE.
IN-100-17	AN EXTREME CLOSE-UP, LOOKING NORTH, OF ONE EDGE

OF THE SOUTHWEST SPANDREL ARCH. DETERIORATION OF

Putnam County Bridge #111 (Dills Ford Bridge) HAER No. IN-100 (Page 3)

THE CONCRETE HAS EXPOSED THE CROSS-TIED REINFORCEMENT SYSTEM TYPICAL OF LUTEN DESIGNED BRIDGES.

- IN-100-18 THIS VIEW, LOOKING NORTHEAST AND UPWARD, SHOWS
 THE CAST PANEL CONTAINING THE CONSTRUCTION DATE,
 WHICH IS LOCATED ABOVE THE CENTRAL PIER.
 ADDITIONAL I-SECTIONS HAVE BEEN USED TO STABILIZE
 THE BRIDGE SLIPPAGE.
- IN-100-19 A CLOSE-UP VIEW OF THE EAST ABUTMENT OF THE BRIDGE, LOOKING NORTH. SEAM AND FORM LINES ARE VISIBLE IN THE CONCRETE.
- IN-100-20

 A PHOTOGRAPH OF A BLUEPRINT, IN FRAGILE
 CONDITION, SHOWING THE DESIGNER'S REINFORCING
 SYSTEM, ELEVATIONS, SECTIONS AND PARTIAL
 FOUNDATION PLANS. THE ORIGINAL IS IN THE PUTNAM
 COUNTY SURVEYOR'S OFFICE, COUNTY COURTHOUSE,
 GREENCASTLE, INDIANA. (FOR CLARITY, AN 8"X10"
 ENLARGEMENT FROM THE ORIGINAL 4"X5" NEGATIVE HAS
 BEEN PROVIDED.)

Key to Photographs
Putnam County Bridge #111
HAER No.IN-100 (Page 4)

